



MICRON_i300 microSD Card - Firmware Maintenance Release

PCN: 34318

Published: 2021-08-10

Type: Firmware Revision

Description: New firmware release 29.100.50 is replacing current production firmware. The key changes are:

1. Feature & performance enhancements
2. System stability improvements
3. General error and protocol improvements

Refer to attached firmware release note for more details.

Cards will begin shipping Sep 15, 2021 with the new firmware.

Reason: Improved Product Quality and Reliability

Product Affected: Micron i300 microSDXC UHS-I Card

Affected Micron Part Number	Recommended Replacement	Customer Part Number
<u>CARD</u>		
MTSD128AKC7MS-1WT		557-MTSD128AKC7MS-1WT-ND
MTSD128AKC7MS-2WT		
MTSD1T0AKC7MS-1WT		557-MTSD1T0AKC7MS-1WT-ND
MTSD1T0AKC7MS-2WT		
MTSD256AKC7MS-1WT		
MTSD256AKC7MS-2WT		
MTSD512AKC7MS-1WT		
MTSD512AKC7MS-2WT		

*Materials that have been ordered are in **bold**.

Method of Identification: New part number suffix is -BK07, etched on the back of the microSD card

Micron Sites Affected: Subcontractor

Sample Available: 2021-08-02

Product Ship Date: 2021-09-15

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments
