



Product Change Notification

TE Connectivity

Product Change Notification: E-14-009319

PCN Date: 23-JUN-14

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Appliances electrical connector

Description of Changes
Bring Part revision in-line with drawing revision

Reason for Changes:
Document Clarification. Part and Drawing revision mismatch

Estimated Dates:

| | |
|--|--|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 31-JUL-2014 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 1-154719-0 | NO | | | | | |
| 1-160759-2 | NO | | | | | |
| 1-725996-2 | NO | | | | | |
| 1217061-1 | NO | | | | | |
| 1217062-1 | NO | | | | | |
| 140723-2 | NO | | | | | |
| 150500-2 | NO | | | | | |
| 150545-2 | NO | | | | | |
| 151667-2 | NO | | | | | |
| 154717-4 | NO | | | | | |
| 154719-1 | NO | | "0-0154719-1" | | | |
| 154719-2 | NO | | | | | |
| 160625-2 | NO | | | | | |
| 160655-2 | NO | | "F49671-000", "AMPS-0-0160655-2" | | | |
| 160655-4 | NO | | | | | |
| 160655-6 | NO | | | | | |
| 160786-2 | NO | | | | | |
| 160859-4 | NO | | | | | |
| 160860-4 | NO | | | | | |
| 160887-4 | NO | | | | | |
| 160913-4 | NO | | | | | |
| 160917-3 | NO | | | | | |
| 160927-4 | NO | | | | | |
| 170002-4 | NO | | | | | |
| 170002-5 | NO | | | | | |
| 170030-1 | NO | | "0-0170030-1" | | | |
| 170030-2 | NO | | | | | |
| | | | | | | |

| | | | | | |
|----------------------------|----|--|--|--|--|
| 170048-4 | NO | | | | |
| 170324-1 | NO | | "0-0170324-1" | | |
| 170328-1 | NO | | | | |
| 175179-1 | NO | | | | |
| 180906 | NO | | "AMPS-0-0180906-0", "F33331-000", "0-0180906-0" | | |
| 182490-2 | NO | | | | |
| 2-520335-2 | NO | | | | |
| 280080-2 | NO | | | | |
| 280755-4 | NO | | | | |
| 280756-4 | NO | | | | |
| 341001-6 | NO | | | | |
| 342368-1 | NO | | "CU3083-000", "AMPS-0-0342368-1" | | |
| 41450-1 | NO | | | | |
| 41480 | NO | | | | |
| 41531-1 | NO | | | | |
| 41772-1 | NO | | | | |
| 42098-1 | NO | | | | |
| 42241-1 | NO | | | | |
| 42400-1 | NO | | | | |
| 42437-5 | NO | | | | |
| 42452-1 | NO | | "0-0042452-1" | | |
| 42486-3 | NO | | | | |
| 42563-2 | NO | | | | |
| 42563-8 | NO | | | | |
| 42563-9 | NO | | | | |
| 42802-1 | NO | | | | |
| 5-160446-2 | NO | | | | |
| 5-160558-9 | NO | | | | |
| 5-160667-2 | NO | | | | |
| 520987-1 | NO | | | | |
| 521317-1 | NO | | | | |
| 521583-2 | NO | | | | |
| 6-160448-2 | NO | | | | |
| 6-160449-5 | NO | | | | |
| 60080-2 | NO | | | | |
| 60487-1 | NO | | | | |
| 60932-2 | NO | | | | |
| 61400-1 | NO | | | | |
| 61492-3 | NO | | | | |
| 61687-2 | NO | | | | |
| 61945-2 | NO | | | | |
| 62050-2 | NO | | | | |
| 62057-1 | NO | | | | |
| 63097-2 | NO | | | | |
| 63306-1 | NO | | | | |
| 63306-2 | NO | | | | |
| 63609-1 | NO | | | | |
| 63609-2 | NO | | | | |
| 63757-2 | NO | | | | |
| 63854-1 | NO | | | | |
| 63933-1 | NO | | | | |
| 63951-1 | NO | | | | |
| 640249-1 | NO | | | | |
| 770642-1 | NO | | | | |

| | | | | | | |
|--------------------------|----|--|----------------------------------|--|--|--|
| 925387-1 | NO | | | | | |
| 925856-1 | NO | | "CM1530-000", "AMPS-0-0925856-1" | | | |
| 926539-5 | NO | | | | | |
| 926539-6 | NO | | "0-0926539-6" | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 1-725996-2 | NO | | | | | | |
| 160859-4 | NO | | | | | | |
| 42098-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1-154719-0 | NO | | | | | | |
| 1217061-1 | NO | | | | | | |
| 1217061-1 | NO | | | | | | |
| 1217062-1 | NO | | | | | | |
| 1217062-1 | NO | | | | | | |
| 140723-2 | NO | | | | | | |
| 150545-2 | NO | | | | | | |
| 154719-1 | NO | | | "0-0154719-1" | | | |
| 154719-2 | NO | | | | | | |
| 160655-4 | NO | | | | | | |
| 160786-2 | NO | | | | | | |
| 160786-2 | NO | | | | | | |
| 160859-4 | NO | | | | | | |
| 160860-4 | NO | | | | | | |
| 160887-4 | NO | | | | | | |
| 160913-4 | NO | | | | | | |
| 160927-4 | NO | | | | | | |
| 170002-4 | NO | | | | | | |
| 170002-4 | NO | | | | | | |
| 170030-1 | NO | | | "0-0170030-1" | | | |
| 170030-2 | NO | | | | | | |
| 170324-1 | NO | | | "0-0170324-1" | | | |
| 170328-1 | NO | | | | | | |
| 180906 | NO | | | "AMPS-0-0180906-0", "F33331-000", "0-0180906-0" | | | |
| 2-520335-2 | NO | | | | | | |
| 280080-2 | NO | | | | | | |
| 341001-6 | NO | | | | | | |

| | | | | | | | |
|----------------------------|----|--|--|----------------------------------|--|--|--|
| 342368-1 | NO | | | "CU3083-000", "AMPS-0-0342368-1" | | | |
| 342368-1 | NO | | | "CU3083-000", "AMPS-0-0342368-1" | | | |
| 41450-1 | NO | | | | | | |
| 41531-1 | NO | | | | | | |
| 42400-1 | NO | | | | | | |
| 42437-5 | NO | | | | | | |
| 42452-1 | NO | | | "0-0042452-1" | | | |
| 42486-3 | NO | | | | | | |
| 42563-2 | NO | | | | | | |
| 42563-2 | NO | | | | | | |
| 42563-8 | NO | | | | | | |
| 42563-9 | NO | | | | | | |
| 42802-1 | NO | | | | | | |
| 520987-1 | NO | | | | | | |
| 521317-1 | NO | | | | | | |
| 521583-2 | NO | | | | | | |
| 6-160448-2 | NO | | | | | | |
| 6-160448-2 | NO | | | | | | |
| 6-160449-5 | NO | | | | | | |
| 60080-2 | NO | | | | | | |
| 60487-1 | NO | | | | | | |
| 60932-2 | NO | | | | | | |
| 61400-1 | NO | | | | | | |
| 61492-3 | NO | | | | | | |
| 61687-2 | NO | | | | | | |
| 61945-2 | NO | | | | | | |
| 62050-2 | NO | | | | | | |
| 62057-1 | NO | | | | | | |
| 62057-1 | NO | | | | | | |
| 63097-2 | NO | | | | | | |
| 63097-2 | NO | | | | | | |
| 63306-1 | NO | | | | | | |
| 63306-2 | NO | | | | | | |
| 63609-1 | NO | | | | | | |
| 63609-2 | NO | | | | | | |
| 63757-2 | NO | | | | | | |
| 63854-1 | NO | | | | | | |
| 63933-1 | NO | | | | | | |
| 63951-1 | NO | | | | | | |
| 640249-1 | NO | | | | | | |
| 640249-1 | NO | | | | | | |
| 770642-1 | NO | | | | | | |
| 925387-1 | NO | | | | | | |
| 925856-1 | NO | | | "CM1530-000", "AMPS-0-0925856-1" | | | |
| 925856-1 | NO | | | "CM1530-000", "AMPS-0-0925856-1" | | | |
| 926539-5 | NO | | | | | | |
| 926539-6 | NO | | | "0-0926539-6" | | | |