

November 26, 2014

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC14054 – Product Discontinuance / Obsolescence Notification**

You are hereby provided notice that the Intersil products included on the attached parts list (appendix) are being discontinued. As a valued customer, and one that has previously purchased one or more of such parts, Intersil Corporation is pleased to offer you a final life-of-type procurement for these parts. Recognizing that you will need some time to analyze your requirements, Intersil will accept orders for these products through the LTB (Life of Type Buy) / WITHDRAWN date provided in the attached list. All shipments under such orders shall be scheduled no later than the SHIP / OBSOLETE date provided. Intersil will attempt to honor all such purchase orders and scheduled delivery dates, but reserves the right to not accept new orders or to cancel existing orders if such orders cannot be filled through reasonable commercial effort.

Please review the list and make adjustments as necessary in your database.

The information contained herein is intended for the recipients use only. Please limit the distribution of this material to those individuals within your immediate organization having a need to act upon the information. In the event that additional distribution outside of your internal organization is necessary, please notify Intersil and the distribution list for discontinued products will be updated as appropriate.

If you are considering a redesign, and require assistance, please contact your local Sales or Rep office, or the Intersil Corporate Line, 1-888-468-3774, for our Central Applications Department.

Regards,



Jeffrey Touvell

Intersil Corporation

PLC14054

CC: J. Rye S. Gupta M. Bennett J. Brewster

Appendix

Exact Intersil Part # No other variation is being impacted.	Notice PLC14054 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
5962F0052301QXC	26-Nov-2014	26-May-2015	26-Nov-2015	5962F0052302VXC
5962F0052301QYC	26-Nov-2014	26-May-2015	26-Nov-2015	5962F0052302VYC
5962F0052301V9A	26-Nov-2014	26-May-2015	26-Nov-2015	5962F0052302V9A
5962F0052301VXC	26-Nov-2014	26-May-2015	26-Nov-2015	5962F0052302VXC
5962F0052301VYC	26-Nov-2014	26-May-2015	26-Nov-2015	5962F0052302VYC
EL5308IUZ-T7S2490	26-Nov-2014	26-Nov-2015	26-May-2016	EL5308IUZ-T13
HIN202EIBNZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIN202EIBNZ-T
HIN206EIAZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIN206EIAZ-T
HIN211ECAZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIN211ECAZ-T
HIP1011CBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIP1011CBZA-T
HIP1011DCAZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIP1011DCAZA-T
HIP1012ACBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIP1012ACBZA-T
HIP2120FRTBZ	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2120FRTBZ-T	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2121FRTBZ	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2121FRTBZ-T	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2122FRTBZ	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2122FRTBZ-T	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2123FRTBZ	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP2123FRTBZ-T	26-Nov-2014	26-May-2015	26-Nov-2015	None
HIP6004ECBZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIP6004ECBZ-T
HIP6301VCBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	None
HIP6601BCBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	HIP6601BCBZA-T
ICL3221ECAZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ICL3221ECAZ-T
ICL3221ECAZA-TS2490A	26-Nov-2014	26-Nov-2015	26-May-2016	ICL3221ECAZ-T
ICL3221ECAZA-TS2490S	26-Nov-2014	26-Nov-2015	26-May-2016	ICL3221ECAZ-T
ISO-1009RH/SAMPLE	26-Nov-2014	26-May-2015	26-Nov-2015	ISO-1009EH/SAMPLE
ISO-1009RH-Q	26-Nov-2014	26-May-2015	26-Nov-2015	ISO-1009EH-Q
IS2-1009RH/PROTO	26-Nov-2014	26-May-2015	26-Nov-2015	IS2-1009EH/PROTO
IS2-1009RH-8	26-Nov-2014	26-May-2015	26-Nov-2015	IS2-1009EH-Q
IS2-1009RH-Q	26-Nov-2014	26-May-2015	26-Nov-2015	IS2-1009EH-Q
ISL1541IRZ	26-Nov-2014	26-May-2015	26-Nov-2015	None
ISL1541IRZ-T13	26-Nov-2014	26-May-2015	26-Nov-2015	None
ISL1541IRZ-T7	26-Nov-2014	26-May-2015	26-Nov-2015	None
ISL28191FRUZ-T7S2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL28191FRUZ-T7
ISL59447IRZ-T7S2490	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL59482IRZ-T13S2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL59482IRZ-T13
ISL6115ACBZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6115ACBZ-T
ISL6116CBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6116CBZA-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC14054 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL6117CBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6117CBZA-T
ISL6118HIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6118HIBZA-T
ISL6119HIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6119HIBZA-T
ISL6119LIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6119LIBZA-T
ISL6121LIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6121LIBZA-T
ISL6123IRZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6123IRZA-T
ISL6144IVZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6144IVZA-T
ISL6227CAZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL6262ACRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6262ACRZ-T
ISL6262CRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6262CRZ-T
ISL6312CRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6312CRZ-T
ISL6336CRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6336CRZ-T
ISL6353CRTZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6353CRTZ-T
ISL6506BCBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6506BCBZA-T
ISL6524ACBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6524ACBZA-T
ISL6525CBZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6525CBZ-T
ISL6537ACRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6537ACRZ-T
ISL6537CRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6537CRZ-T
ISL6545CBZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6545CBZ-T
ISL6556BCBZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6556BCBZ-T
ISL6558CBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6558CBZA-T
ISL6620CRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL6620CRZ-T
ISL6700IRZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL6700IRZ-T	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL6720AARZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL6720AARZ-T	26-Nov-2014	26-Nov-2015	26-May-2016	None
ISL78420ARTAZ	26-Nov-2014	26-Nov-2015	26-May-2016	ISL78420AVEZ
ISL78420ARTAZ-T	26-Nov-2014	26-Nov-2015	26-May-2016	ISL78420AVEZ-T
ISL8488EIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL8488EIBZA-T
ISL8489EIBZA-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL8489EIBZ-T
ISL8500IRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL8500IRZ-T
ISL9107IRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL9107IRZ-T
ISL9500CVZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL9500CVZ-T
ISL9519CHRZ	26-Nov-2014	26-Nov-2014	26-Dec-2014	None
ISL9519CHRZ-T	26-Nov-2014	26-Nov-2014	26-Dec-2014	None
ISL95831HRTZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL95831HRTZ-T
ISL95836HRTZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL95836HRTZ-T

Exact Intersil Part # No other variation is being impacted.	Notice PLC14054 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
ISL95870BHRZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL95870BHRZ-T
ISL97801ARZ-TS2490	26-Nov-2014	26-Nov-2015	26-May-2016	ISL97801ARZ-TK
ISYE-1009RH/PROTO	26-Nov-2014	26-May-2015	26-Nov-2015	ISYE-1009EH/PROTO
ISYE-1009RH-8	26-Nov-2014	26-May-2015	26-Nov-2015	ISYE-1009EH-Q
ISYE-1009RH-Q	26-Nov-2014	26-May-2015	26-Nov-2015	ISYE-1009EH-Q
X9251US24IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9251US24ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9259US24ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9408YV24ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409WS24ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409YS24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9409YS24Z	26-Nov-2014	26-Nov-2015	26-May-2016	None

Exact Intersil Part # No other variation is being impacted.	Notice PLC14054 Issue Date	LTB / Withdrawn Date	Ship / Obsolete Date	Replacement / Similar / Re-Design
X9409YV24IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WS16ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9420WV14ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YS16ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14IZ	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14IZ-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14IZ-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14IZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14Z	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14Z-2.7	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14Z-2.7T1	26-Nov-2014	26-Nov-2015	26-May-2016	None
X9429YV14ZT1	26-Nov-2014	26-Nov-2015	26-May-2016	None