



# Product Change Notice

PCN Number: 17-0310-03  
Issue Date: 17-APRIL-2017

Exar Corporation

[www.exar.com](http://www.exar.com) | Support: [customersupport@exar.com](mailto:customersupport@exar.com)

**PRODUCTS AFFECTED:**

SP3232ECP-L | SP3232EEP-L

**CHANGE CATEGORY:**

- |   |                                    |   |
|---|------------------------------------|---|
| <input checked="" type="checkbox"/> Material              | <input type="checkbox"/> Process   | <input type="checkbox"/> Package          |
| <input type="checkbox"/> Design                           | <input type="checkbox"/> Datasheet | <input type="checkbox"/> Packing/Shipping |
| <input checked="" type="checkbox"/> Other: Alternate Site |                                    |   |

**DESCRIPTION OF CHANGE:**

Qualification of copper wire bonding assembly and alternate foundry subcon, TSMC.

**IMPACT OF CHANGE:**

There is no change to product form, fit or function.

**TARGET IMPLEMENTATION DATE:** 17-JULY-2017

Please contact customer support ([customersupport@exar.com](mailto:customersupport@exar.com)) for sample date availability or qualification data

**PROPRIETARY INFORMATION**

THIS DOCUMENT CONTAINS INFORMATION WHICH IS THE EXCLUSIVE PROPERTY OF EXAR CORPORATION. DISTRIBUTION, REPRODUCTION OR USE BY OTHERS IS NOT PERMITTED WITHOUT THE EXPRESS WRITTEN AUTHORIZATION OF EXAR CORPORATION.