



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000853

DATE: 05-May-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX2676EVKIT+	N/A			Part reactivated from prior notice: M000790
Lead-Free Conversion	MAX1873SEEE	MAX1873SEEE+	05-May-2018	04-Nov-2018	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX890LESA	MAX890LESA+	05-May-2018	04-Nov-2018	Part is leaded. Request information on lead-free version
Discontinuance	806-0714-25+W	806-0714-25+	05-May-2017	05-May-2017	The part was not released
Discontinuance	DS1083LR+T	N/A	05-May-2019	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1210+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1210N+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1210S+TRL	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1833-15+T&R	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS1844-100+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1844E-100+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1844E-100+T&R	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1844S-010+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1844S-010+T&R	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS1844S-100+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS2762BE+025	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS2764AE+025	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS2764BE+025	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS2764BE+025/T&R	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS4155D+	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS4155P+	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS4302Z-020+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4510U-10+	DS4510U-15+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	DS4M133P+33	DS4M133D+33	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	DS4M200P+33	DS4M200D+33	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	MAX1359BETL+	N/A	05-May-2017	05-May-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 05-Jun-2017

Discontinuance	MAX15040EVKIT+	MAX15050EVKIT+	05-May-2017	05-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX15040EWE+	MAX15050EWE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX1645BEVKIT+	N/A	05-May-2017	05-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX16503GFI+	MAX16503GFN+	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	MAX16503GFI+T	MAX16503GFN+T	05-May-2017	05-May-2017	The part was not released
Discontinuance	MAX231MJD	MAX231MJD/883B	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	MAX2680EVKIT	MAX2680EVKIT#	05-May-2017	05-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX3408EUK+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX34463EXQA1+W	MAX34463EXQA2+	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	MAX44206AUA+	N/A	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX5945EVKIT	N/A	05-May-2017	05-May-2017	EVKIT is No Longer Supported
Discontinuance	MAX6670AUB40+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB45+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB50+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB55+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB60+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB65+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB65+T	MAX31760AEE+T	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	MAX6670AUB70+	MAX31760AEE+	05-May-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	VT1115SCX	VT1115SFCX	05-May-2017	05-May-2017	Part is leaded, and a lead-free replacement exists
Discontinuance	VT266AWFQR-ADJ-008	VT266AWFQX-ADJ-008	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	VT266WFQR-ADJ	VT266WFQX-ADJ	05-May-2017	05-May-2017	Part can no longer be manufactured
Discontinuance	ZA9L102BNW2CSGA431	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L1033NW2CSGA429	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L1037NW2CSGA426	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L103FNW2CSGA412	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L1069NW2CSGA422	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L106DNW2CSGA434	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured
Discontinuance	ZA9L10D1NW2CSGA499	MAX32590-L5S+	04-Nov-2018	04-Nov-2018	Part can no longer be manufactured