



Product Change Notification / SYST-03BYDF167

Date:

04-Jan-2022

Product Category:

Ethernet Bridges

PCN Type:

Document Change

Notification Subject:

Data Sheet - LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller

Affected CPNs:

[SYST-03BYDF167_Affected_CPN_01042022.pdf](#)

[SYST-03BYDF167_Affected_CPN_01042022.csv](#)

Notification Text:

SYST-03BYDF167

Microchip has released a new Product Documents for the LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller of devices. If you are using one of these devices please read the document located at [LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller](#).

Notification Status: Final

Description of Change:

1) Table 3-2, "Pin Descriptions": TEST pin description modified.

Impacts to Data Sheet: See above details.

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 04 Jan 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

LAN7800 - SuperSpeed USB 3.1 Gen 1 10/100/1000 Ethernet Controller

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

LAN7800-I/VSX

LAN7800-I/Y9X

LAN7800/VSX

LAN7800/Y9X

LAN7800T-I/VSX

LAN7800T-I/Y9X

LAN7800T/VSX

LAN7800T/Y9X