



Process Change Notice #1206221

User Registration

Register today to create your account on Silabs.com. Your personalized profile allows you to receive technical document updates, new product announcements, "how-to" and design documents, product change notices (PCN) and other valuable content available only to registered users. <http://www.silabs.com/profile>

PCN Date: 6/22/2012		Effective Date: 12/22/2012	
Title: 28-SSOP Package Devices End of Life (EOL) and Last Time Buy (LTB)			
Originator: Jimmy Ma		Phone: 1.408.702.1324	Dept: Marketing
Customer Contact: Kathy Haggar		Phone: 1.512.532.5261	Dept: Inside Sales
PCN Type: <input type="checkbox"/> Datasheet <input type="checkbox"/> Foundry <input type="checkbox"/> Packing <input type="checkbox"/> Product Revision <input type="checkbox"/> Assembly <input type="checkbox"/> Labeling <input checked="" type="checkbox"/> Discontinuance <input type="checkbox"/> Test <input type="checkbox"/> Other			
Last Order Date: 12/22/2012			
PCN Details			
Description of Change: Silicon Laboratories is announcing the End of Life (EOL) and Last Time Buy (LTB) for the products listed below. All orders, including Last Time Buy orders, for these products must be placed by the PCN Effective Date (12/22/2012) and have a customer requested delivery date within 12 months (6/22/2013) of the PCN Date which is 6/22/2012. Any orders with a customer request date between the PCN Effective Date, (12/22/2012) and 12 months from the PCN Date, (6/22/2012) will be non-cancellable and non-returnable. Silicon Laboratories recommends the Si5350, Si52146, Si5335, and Si52132-A11A for clock generator replacement parts and SL23EP09 for clock buffer replacements parts. The recommended replacement parts are easier to design-in, offer lower BOM cost, lower power consumption, and provide better performance. They are not pin to pin compatible to the EOL devices. The recommended device datasheets are available from www.silabs.com and / or Silicon Laboratories Sales representatives.			
Affected EOL / LTB Product		Silicon Labs suggested replacement parts	
CY28353OXC-2		Si52146	
CY28353OXC-2T		Si52146	
CY28508OXC		Si5335	
CY28508OXCT		Si5335	
CYI9531OXC		Si52132-A11A	
CYI9531OXCT		Si52132-A11A	
CYW137OXC		Si5350	
CYW137OXCT		Si5350	
CYW256OXC		SL23EP09	
CYW256OXCT		SL23EP09	
W40S11-02H		SL23EP09	
W40S11-02HT		SL23EP09	

